


131 (E1)

T CURVE




MISURA	CODICE	DIMENSIONI (mm)				Peso (gr)
		a	c	z	z3	
1/2"	13101/5003	45	24	32	11	241
3/4"	13101/5004	50	28	35	13	332
1"	13101/5005	63	33	46	16	457
1 1/4"	13101/5006	76	40	57	21	685
1 1/2"	13101/5007	85	43	66	24	1033
2"	13101/5008	102	53	78	29	1400
2 1/2"	13101/5009	115	62	88	35	2340
3"	13101/500A	127	70	97	40	3755
4"	13101/500C	165	87	129	51	6260

1/5 - 1= Nera - 5= Zincata

132 (E2)

T DA DUE CURVE




MISURA	CODICE	DIMENSIONI (mm)		Peso (gr)
		a	z	
1/2"	13201/5003	45	32	192
3/4"	13201/5004	50	35	385
1"	13201/5005	63	46	598
1 1/4"	13201/5006	76	57	798
1 1/2"	13201/5007	85	66	980
2"	13201/5008	102	78	1920

1/5 - 1= Nera - 5= Zincata

133

T



MISURA	CODICE	DIMENSIONI (mm)			Peso (gr)
		a	b	z	
3/8"	13301/5002	22	31	12	83
1/2"	13301/5003	25	38	12	101
3/4"	13301/5004	33	45	18	190
1"	13301/5005	39	53	22	325

1/5 - 1= Nera - 5= Zincata